INSPECTIONS COME WITH A LINK TO VIEW ALL PICTURES & VIDEOS FROM THE INSPECTION AS WELL.

PPI VEHICLE INSPECTION

Please complete as much of this form as possible to help Customer make the most educated decision.

Customer Email	[redacted]

TECHNICIAN

Technician First Name	[redacted]
Technician Phone Number	[redacted]

PLEASE MARK ALL BOXES THAT APPLY:

VEHICLE INFORMATION:

Year	2016
Make	SUBARU
Model	Forester
Color	White
VIN Number	[redacted]
Mileage	178935
Keys	Manual Key + Key Fob

EXTERIOR:

Paint Condition	Good Condition, Other: Light scratching near rear driver side tail light.
Body/Frame Condition	Good Condition
Windows/Windshield/Glass Condition	Good Condition
Lights (Head Lights/Tail Lights)	1 Not Functioning, Other: Rear driver side tail light is out.
Tires (You Should Be Selecting 4 Options, 1 For Each Tire)	Front Driver - Good Condition, Rear Driver - Good Condition, Front Passenger - Good Condition, Rear Passenger - Good Condition
Rims/Wheels (You Should Be Selecting 4 Options, 1 For Each Wheel)	Front Driver - Good Condition, Rear Driver - Good Condition, Front Passenger - Good Condition, Rear Passenger - Good Condition

INTERIOR

Appearance	Clean, Good Smell
Please use this GUIDE for the indicator lights.	
Dashboard Light Indicators	NONE
Heating System	Functioning
A/C System	Functioning, Cold
Locks	All Functioning
Sunroof	All Functioning
Front Driver Seat	Good Condition, Normal Wear & Tear, Cracked/Ripped, Other: Small rip/crack on lap of seat.
Other Seats	Good Condition, Normal Wear & Tear
Upholstery	Good Condition, Normal Wear & Tear
Water Damage	No Signs of Water Damage
Please Upload Video (avg 30 - 60 secs) of ALL Angles of Interior (Including All Previously Mentioned Items), Photo if Video isn't possible.	80402627537__CDC07C7E-842D-4CF4-8731-50C0D413313E.MOV

UNDER THE HOOD

Coolant	Less than 1/2, Almost Empty
Engine Oil	Clean, Full
Transmission Fluid	Other: Sealed CSV Case
Brake Fluid	Full
Belts & Hoses	All Intact, All Functional
Battery	Functioning, Other: Battery Tested: 12.0 v, Load Tested: 9.0 v
Radiator	Functioning, Clean
Under The Hood Notes	Looks good.
Please Upload Video (avg 30 - 60 secs) of ALL Angles of UNDER THE HOOD (Including All Previously Mentioned Items), Photo if Video isn't possible.	80402679808__2BE1381A-2979-4FD0-8735-1D3E0D05EF49.MOV

UNDERBODY

Exhaust System	Functioning, Rusted, Original Catalytic Converter = Present
Please Upload Video (avg 30 - 60 secs) of ALL Angles of the UNDERBODY (Including All Previously Mentioned Items), Photo if Video isn't possible.	80402693010__8D23765A-59D9-4494-A8D7-599EDEEEF1E5.MOV

COMPUTER DIAGNOSTIC

OBD Scan Results	No Codes Found
Please describe all Codes found	Last time codes cleared 65k miles ago.
Please Upload Images of all Codes found	image.jpg

TESTING THE VEHICLE

Ignition	Starts
Idling	Good Condition
Acceleration	Good Condition
Transmission	Shifts Roughly, Other: CVT looks normal temperature, but shifting issues between 20-35 mph.
Brakes	Functioning
Rotors	Functioning

OVERALL NOTES:

Notes	Clean looking vehicle that looks to have been maintained but experience transmission shifting issues between 20-35 mph. Higher speeds seem ok.